Report Title - Fire Safety Equipment Inspection

Completed By - tim@theavrlab.com

THE AVR LAB
1800 287 522

Started - 27 Oct 2022 at 09:11:29

Completed - 27 Oct 2022 at 09:14:42

Duration - 0.00:03

Actual Duration - 0.00:02

Completed Steps

Please watch the video below

Completed By - tim@theavrlab.com
Total Duration - 00:00:06 **Active Duration -** 00:00:06
to start this work flow

This step has no value.

Monthly Fire Extinguisher Visual inspection

Completed By - tim@theavrlab.com
Total Duration - 00:00:07 **Active Duration -** 00:00:07
In this Audit, we will conduct a visual inspection of the Fire Extinguisher on site to ensure equipment is fit for use.

This step has no value.

Does the Fire Extinguisher have

Completed By - tim@theavrlab.com
Total Duration - 00:00:00 **Active Duration -** 00:00:00
a safety pin in place? - Reference the image below

Yes

Report Title - Fire Safety Equipment Inspection

Completed By - tim@theavrlab.com

THE AVR LAB
1800 287 522

Started - 27 Oct 2022 at 09:11:29

Completed - 27 Oct 2022 at 09:14:42

Duration - 0.00:03

Actual Duration - 0.00:02

Please take a photo of the

Completed By - tim@theavrlab.com
Total Duration - 00:00:37 **Active Duration -** 00:00:37
fire extinguisher with the safety pin in place

Is there a security tie

Completed By - tim@theavrlab.com
Total Duration - 00:00:04 **Active Duration -** 00:00:04
in place on the Fire Extinguisher? - Refer to image below

Yes

Please take a photo of the security tie in place

Completed By - tim@theavrlab.com
Total Duration - 00:00:21 **Active Duration -** 00:00:21

Report Title - Fire Safety Equipment Inspection

Completed By - tim@theavrlab.com

THE AVR LAB
1800 287 522

Started - 27 Oct 2022 at 09:11:29

Completed - 27 Oct 2022 at 09:14:42

Duration - 0.00:03

Actual Duration - 0.00:02

Which zone is the needle gauge in?

Completed By - tim@theavrlab.com

Total Duration - 00:00:03 **Active Duration -** 00:00:03

1. Green Zone 2. Red Zone 0r is it 3. Unclear - Reference image below

Green

Please take a picture of the Needle Gauge

Completed By - tim@theavrlab.com

Total Duration - 00:00:26 **Active Duration -** 00:00:26

- Reference Image Below

Please dictate any other observations

Completed By - tim@theavrlab.com

Total Duration - 00:00:24 **Active Duration -** 00:00:24

for reporting purposes

this dry Pada fire extinguisher is nearing its battery died

Capture video of Fire Extinuisher inspection

Completed By - tim@theavrlab.com

Total Duration - 00:00:08 **Active Duration -** 00:00:08

ready to use. for reporting purposes (Optional)

This step has no value.

Report Title - Fire Safety Equipment Inspection

Completed By - tim@theavrlab.com

THE AVR LAB
1800 287 522

Started - 27 Oct 2022 at 09:11:29

Completed - 27 Oct 2022 at 09:14:42

Duration - 0.00:03

Actual Duration - 0.00:02

End of Fire Extinguisher Visual Inspection

Completed By - tim@theavrlab.com

Total Duration - 00:00:03 **Active Duration -** 00:00:03

please play the video below Please ask one of our staff for a copy of this report

This step has no value.

Cancelled Steps

Does the Fire Extinguisher have

Completed By - tim@theavrlab.com

Total Duration - 00:00:03 **Active Duration -** 00:00:03

a safety pin in place? - Reference the image below

No

Please take a photo as evidence of

Completed By - tim@theavrlab.com

Total Duration - 00:00:00 **Active Duration -** 00:00:00

the fire extinguisher to document the missing safety pin

This step has no value.